

2023 YBC Work Camp

I. Bridge -

Impact out all the lag bolts on the planks.
Remove the cable system for the A-frames.
Remove the planks starting from the far side and stack by the other stack.
Remove the stringers, take off the coating and stack near the horse shoe pits.

II. Roofs -

Change out screws and caulk snow guard screw holes on the lodge, chapel & King.
Inspect vent boots and replace or reseal as needed.
Check chimney seals and roof jack on back of lodge.
Replace chimneys on the Tamarack (possibly two other cabins).

III. Seal logs on 3 cabins - (OKC)

King, Alice (2023); Jail. Pine, Cottonwood, Tamarack, (2026); Hill, Rose Arbor, Texas, Poplar (2029); Lodge, Chapel (2032).

IV. Woodshed restock -

Split wood to replenish wood pile.

V. Bleachers - (OKC)

Inspect and replace seats and foot rests as needed.
Inspect framework and tighten braces as needed.

VI. Alice bedroom ceilings -

Remove sheetrock ceiling tiles and replace with fiber ceiling tiles.
Replace whiteboards next to rooms in the halls as needed.

VII. Alice outside steps -

Inspect steps and non-skid tread and repair as needed.

VIII. Freezer / Cooler -

Replace door seals on both doors (If available).
Caulk interior wall corners in freezer unit (Prior to start up).
Investigate taller narrower shelf for condiments just inside the cooler on the right?

IX. Salad Room Entry -

Replace entry door with 80" x 36" steel door & storm door.

X. Tamarack Shower -

Upgrade downstream shower stall (As available).

XI. Yard work - (OKC)

Mow/weed-eat grounds.
Clear brush along creekside.
Install swings & tether balls.
Repair playground structures.

XII. Broken windows -

Check and measure for replacements - Cottonwood, Rose Arbor, Chapel?

XIII. Yard lights -

Changeout mercury vapor with 'dawn-to-dusk' LED flood lights.

XIV. Burn pile -

Investigate opportunity to fire the burn pile during 'Selfless' or 'Work Camp'.